

**DUKE POWER COMPANY**

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-4531

October 18, 1984

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Attention: Ms. E. G. Adensam, Chief  
Licensing Branch No. 4

Re: Catawba Nuclear Station  
Docket Nos. 50-413 and 50-414

Dear Mr. Denton:

On July 6, 1984, Duke Power Company submitted a revised Catawba FSAR Table 1.9-1 (Page 16) which addressed NUREG-0737, Item II.K.3.17, Report on Outages of Emergency Core Cooling Systems. That submittal was a restatement of a commitment which is discussed in Section 13.5.2 of the SER.

It has since come to our attention that the Staff had previously made findings on other NTOL's that active participation in the Nuclear Plant Reliability Data System (NPRDS) and compliance with the requirements of 10 CFR 50.73 satisfy the requirements of II.K.3.17.

As an active participant in NPRDS and subject to the requirements of 10 CFR 50.73, it is our conclusion that the separate reporting of emergency core cooling system outage information in accordance with II.K.3.17 is unnecessary and therefore the previously submitted revision to FSAR Table 1.9-1 (Page 16) will not be included in Revision 12.

Very truly yours,

*Hal B. Tucker*  
EET

Hal B. Tucker

ROS:slb

cc: Mr. James P. O'Reilly, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Mr. Robert Guild, Esq.  
Attorney-at-Law  
P. O. Box 12097  
Charleston, South Carolina 29412

8410230133 841018  
PDR ADOCK 05000413  
F PDR

1021  
1/0

Mr. Harold R. Denton, Director  
October 18, 1984  
Page 2

cc: NRC Resident Inspector  
Catawba Nuclear Station

Palmetto Alliance  
2135 1/2 Devine Street  
Columbia, South Carolina 29205

Mr. Jesse L. Riley  
Carolina Environmental Study Group  
854 Henley Place  
Charlotte, North Carolina 28207