



July 26, 1984

Log No. K84-1022  
File: RR 2 (NP-33-84-03)

Docket No. 50-346  
License No. NPF-3

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Gentlemen:

Enclosed is Revision 1 to Licensee Event Report 84-003. The revisions to the report are indicated by a "1" in the left margin of each page.

Please destroy your previous copies of this report and replace with the attached revision.

Yours truly,

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station



Please replace your previous Page 1 to the LER attached with the attached corrected copy.

The corrected copy contains all NPRDS codes which were omitted when Revision 1 was mailed to you on July 26, 1984.

TDM/ljk

Enclosure

cc: Mr. James G. Keppler,  
Regional Administrator,  
USNRC Region III

Mr. Walt Rogers  
DB-1 NRC Resident Inspector

bcc: J. R. Dyer  
J. Hirsch  
J. W. Fay  
R. E. Lapp  
R. G. Staker  
C. M. Rice  
J. R. Albert  
D. A. Huffman  
CNRB Members  
Shift Technical Advisors  
Training Department  
Student Resource Center  
INPO Records Center  
American Nuclear Insurers  
Site Licensing  
SAR-UP Administrator  
Technical Section  
M. Lewczynski  
F. L. Swanger

JCS/001

IE22  
1/1

THE TOLEDO EDISON COMPANY  
8408080506 840726  
PDR ADDCK 05000346  
S PDR

EDISON PLAZA

300 MADISON AVENUE

TOLEDO, OHIO 43652