

**LOUISIANA**


POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

July 25, 1984

W3K84-1707

Q-3-A35.07

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



REFERENCE: Telecon R. Gimelli (LP&L) and L. Martin (NRC Region IV)  
on July 11, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Potentially Reportable Deficiency No. 172  
"Changes to EFW Control System May Not Support Chapter 15 of FSAR"  
Supplemental Report

At the present time, analyses to confirm the selected Steam Generator Level setpoints for the EFCS are being performed. Preliminary analyses indicate that present Steam Generator level setpoints selected for the EFCS are satisfactory. Combustion Engineering has completed system response analysis and the results of completed final engineering analysis, including instrument inaccuracies, will be available by July 27, 1984, at which time the final safety analyses will be performed.

The Final Report will be provided to the USNRC on August 3, 1984.

Very truly yours,

T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:SSTG

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8409090029 840725  
PDR ADOCK 05000382  
S PDR

IS-27/10

Mr. John T. Collins

July 25, 1984

W3K84-1707

Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814