

United States Senate

WASHINGTON, DC 20510-3001


October 25, 1995

Mr. Richard L. Bangart, Director
Office of State Programs
Nuclear Regulatory Commission
Office of Congressional Affairs
1717 H Street, N.W.
Washington, D.C. 20555

Dear Mr. Bangart:

I forward the attached for your consideration. I have told Paul Gunter, Director of the Reactor Watchdog Project of the Nuclear Information and Resource Service (NIRS) that you will respond to his concerns directly. Thank you very much for your time and assistance in this matter.

Sincerely,



Bill Bradley
United States Senator

BB/kc



Nuclear Information and Resource Service

1424 16th Street NW, Suite 601, Washington, DC 20036 202-328-0002; fax: 202-462-2183; e-mail: nirsnet@aol.com

October 19, 1995

The Honorable Bill Bradley
U.S. Senate
731 Hart Senate Office Building
Washington, DC 20510

Dear Sir:

Enclosed please find a copy of a letter sent to Alexander Dromerick, NRC Project Manager for the Oyster Creek nuclear power generating station at Toms River, NJ.

We would greatly appreciate your attention to this age-related deterioration issue at Oyster Creek. We are very concerned that the quick fix employed to repair the cracked core shroud has employed susceptible materials as outlined in the letter to the NRC.

We wish to thank you for your attention to this subject.

Sincerely

A handwritten signature in cursive script, reading 'Paul Gunter', written in black ink.

Paul Gunter, Director
Reactor Watchdog Project