

JOINT DIRECT TESTIMONY OF  
DR. ROBERT N. ANDERSON, et al.

TABLE OF CONTENTS

<u>Subject</u>	<u>Page</u>
<u>INTRODUCTION</u> . . . . .	1
Witness qualification and experience . . . . .	1
Purpose and organization of testimony . . . . .	11
Functions and Requirements for EDGs . . . . .	14
EDG Rating . . . . .	15
Modification of EDGs . . . . .	23
<u>MODEL AE PISTONS</u> . . . . .	25
Cracking of AE Piston Skirts . . . . .	27
FaAA's analysis . . . . .	27
Higher peak firing pressures . . . . .	29
Gap between skirt and crown . . . . .	32
Tensile properties . . . . .	33
Propagation . . . . .	34
Inspections and testing . . . . .	41
Consequences of crack propagation . . . . .	46
Conclusions . . . . .	47
Excessive Piston Side Thrust . . . . .	48
Calculations and effects . . . . .	48
Evidence of excessive side thrust . . . . .	52
FaAA's analysis . . . . .	54
Tin Plating of AE Piston Skirt . . . . .	56

<u>REPLACEMENT CYLINDER HEADS</u> . . . . .	59
Purpose of testimony . . . . .	59
Conclusions . . . . .	62
Relationship to original heads . . . . .	64
Inadequate Design . . . . .	68
Major design issues . . . . .	68
Firedeck thickness . . . . .	70
Non-uniform head stud spacing . . . . .	73
FaAA's analysis . . . . .	73
Changes in Manufacturing Techniques . . . . .	76
Cracking in original heads . . . . .	76
Changes . . . . .	80
FaAA's analysis . . . . .	81
Operating history . . . . .	85
Inspections of Replacement Heads . . . . .	86
By TDI . . . . .	87
At Shoreham . . . . .	89
Cracks in Replacement Heads . . . . .	93
Leaks after EDG shutdown . . . . .	93
Effect on rapid restart capability . . . . .	97
Leakage during operation . . . . .	101
Barring over procedure . . . . .	103
<u>REPLACEMENT CRANKSHAFTS</u> . . . . .	106
Standards for Crankshaft Design . . . . .	109
Rules of ship classification societies and DEMA . . . . .	109

Calculations under Lloyd's rules . . . . .	114
Calculations under IACS rules . . . . .	116
Calculations under ABS rules relating to crankshaft webs . . . . .	118
Calculations under NKK rules and German register . . . . .	120
Calculations under ABS rules on torsional vibrations . . . . .	122
ABS approval and information relied upon by the ABS . . . . .	123
Crankshaft Shotpeening . . . . .	133
Purpose and effects . . . . .	133
Original shotpeening . . . . .	136
Conclusions . . . . .	142
<u>CYLINDER BLOCKS</u> . . . . .	143
Purpose of testimony and conclusions . . . . .	143
Cracking of EDG blocks . . . . .	146
FaAA's analysis . . . . .	147
Acceptance criterion . . . . .	148
Ligament cracks . . . . .	151
FaAA's reliance on non-nuclear block cracks . . . . .	157
FaAA's predictions of cracking . . . . .	159
Material properties . . . . .	171
Abnormal load excursion . . . . .	172
Camshaft gallery area cracks . . . . .	174
Other cracks . . . . .	178
Causes of cracks . . . . .	180
Replacement block on EDG 103 . . . . .	181