



Commonwealth Edison
1400 Opus Place
Downers Grove, Illinois 60515

March 13, 1992

Dr. Thomas E. Murley, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Attn: Document Control Desk

Subject: Byron Station Units 1 and 2
Regulatory Guide 1.97 Compliance
Tac Nos. M57198 and M63250
NRC Docket Nos. 50-454 and 50-455

Reference:(a) May 23, 1991 letter from A. Checchia
to Dr. T.E. Murley

Dear Dr. Murley:

The purpose of this letter is to provide the NRC Staff notification of completion of an activity, to which a commitment was made in prior correspondence. The replacement of the RHR heat exchanger outlet temperature instrumentation with environmentally qualified instrumentation was completed on Byron Unit 1 during the Fall 1991 refueling outage. With completion of this modification, all commitments made for Byron Units 1 and 2 compliance with Regulatory Guide 1.97 are completed. The letter of Reference (a) indicated all other Byron Unit 1 and 2 commitments were completed.

Please direct any questions you may have concerning these matters to this office.

Respectfully,

Terence K. Schuster
Nuclear Licensing Administrator

cc: A.H. Hsia - Project Manager, NRR
W. Kropp - Senior Resident Inspector, Byron
A. Bert Davis - Regional Administrator - RIII

9203200245 920313
PDR ADOCK 05000454
P PDR

ZNLD/867/39

A003
1/0