

Duke Power Company
Catawba Nuclear Generation Department
4800 Concord Road
York, SC 29745

WILLIAM R. MCCOLLUM, JR.
Vice President
(803)831-3200 Office
(803)831-3426 Fax



DUKE POWER

November 13, 1995

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555


Subject: Catawba Nuclear Station
Docket Nos. 50-413 and 50-414
Special Report
Auxiliary Building Filtered Exhaust System

On October 14, 1995, Auxiliary Building Filtered Exhaust (VA) System Pump Room Heater (PRHDS-2B) was declared inoperable.

A blown fuse was discovered upon initial inspection of the heater control panel. A technical investigation will be performed to determine the cause of failure of VA PRHDS-2B. This investigation will be completed and the heater returned to service by January 15, 1996. The tracking document for this investigation is Problem Investigation Process (PIP) 0-C95-02003.

Since this component was not restored to operable status within 7 days pursuant Technical Specification (TS) 3.7.7 b., this special report is being submitted in accordance with TS 6.9.2. This component was entered as Item # C0-95-03099 in the Technical Specification Action Item Logbook for tracking purposes.

Very truly yours,



W. R. McCollum

KEN\SR111395.VA

xc: S. D. Ebnetter, Regional Administrator
R. E. Martin, ONRR
R. J. Freudenberger, SRI

9512010271 951113
PDR ADDCK 05000413
S PDR

TE22
1/0