



300 Madison Avenue
Toledo, OH 43652-0001
419-249-2300

John P. Stetz
Vice President - Nuclear
Davis-Besse

Docket Number 50-346

License Number NPF-3

Serial Number 2345

November 27, 1995

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Revision to Core Operating Limits Report for Cycle 10

Ladies and Gentlemen:

Enclosed is a copy of Revision 1 of the Davis-Besse Nuclear Power Station, Unit 1 (DBNPS) Core Operating Limits Report (COLR) for Cycle 10 Operation. This revision to the COLR is being submitted in accordance with DBNPS Technical Specification 6.9.1.7.

Revision 1 corrects linear heat rate limits specified in Table 4 of the COLR to account for nonconservative assumptions discovered in the Loss of Coolant Accident (LOCA) analysis. This was reported to the Nuclear Regulatory Commission (NRC) under Licensee Event Report (LER) 95-001-00, which was submitted by letter dated February 24, 1995 in accordance with 10 CFR 50.73(a)(2)(ii)(B) and 10 CFR 50.46(a)(3)(ii). Revision 1 also corrects a typographical error in Table 4 of the COLR. This error was in the conservative direction.

Should you have any questions or require additional information, please contact Mr. Peter W. Smith, acting Manager - Regulatory Affairs, at (419) 249-2366.

Very truly yours,

A handwritten signature in dark ink, appearing to read 'John P. Stetz', written over the closing 'yours,'.

MAR/llh

Enclosure

cc: L. L. Gundrum, NRC Project Manager
H. J. Miller, Regional Administrator, NRC Region III
S. Stasek, DB-1 NRC Senior Resident Inspector
Utility Radiological Safety Board

Docket Number 50-346

License Number NPF-3

Serial Number 2345

Enclosure

CYCLE 10

CORE OPERATING LIMITS REPORT

(20 Pages follow)