

50-289-251
(Kistner)

COMMENT OF SEC 84-237 T&I ~~at~~ Rest
Re your Memo of 27 Jul 84.

Cutting the subcooling margin removes not only the "buffer" of string error but also the time that the operators will have to react to the reading before other problems ~~not~~ develop. Also a configuration factor of 1.3°F is really a small difference for an operator to read + calculate under stressful accident conditions.

M. I. LEWIS (215)
6504 BRADFORD TERR 289
PHILA, PA. 19149 5964

M. I. LEWIS
6504 BRADFORD TERR.
PHILA, PA. 19149



Domestic Rate

SEC. USNRC
WASHINGTON, DC. 20555

DS03