



GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 713 838-6631

August 20, 1984
RBG-18701
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011


Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Final Report/DR-138



On July 20, 1984, GSU notified Region IV by telephone that it had determined DR-138 to be reportable under 10CFR50.55(e). This deficiency concerns ITE-Gould Type 2150 overload relays. The attachment to this letter is GSU's final 30-day written report pursuant to 10CFR50.55(e) with regard to this deficiency.

Sincerely,

for 
J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB
JEB/PJD/lp

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

NRC Resident Inspector-Site

INPO

8408300343 840820
PDR ADOCK 05000458
S PDR

IE-27
1/0