




**LOUISIANA**

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

September 5, 1984

W3K84-2105  
Q-3-A35.07.37  
Q-3-A35.07.80  
Q-3-A35.07.93

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiencies Nos. 37, 80, and 93  
Extension Request  
Interim Report

Due to the delay in the schedule for the accomplishment of Post Core Hot Functional Testing, the Final Reports for Significant Construction Deficiency Nos. 37, 80, and 93 are scheduled to be submitted to the USNRC on December 15, 1984.

Very truly yours,

T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:VBR

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8409260572 840905  
PDR ADOCK 05000382  
S PDR

IE-27  
1/0

Mr. John T. Collins  
September 5, 1984  
W3K84-2105  
Page 2

cc: Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814