



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

9/26/84

FILE: B09-13510C
SERIAL: BSEP/84-2024

NRC Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
LICENSEE EVENT REPORT 1-84-17

Gentlemen:

On August 21, 1984, it was discovered that normal system flow within the Unit 1 Residual Heat Removal Service Water (RHRSW) Loop B could not be established. An investigation was begun to determine if the problem affecting RHRSW Loop B was generic to the other RHRSW loops of both Unit 1 and Unit 2. The Licensee Event Report of this event, identified as LER 1-84-17, was to be submitted to your office by September 20, 1984; however, the investigation and evaluation concerning this event is not yet complete. LER 1-84-17 will be submitted by October 22, 1984.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/jlh/LETJH1

Enclosure

cc: Mr. R. C. DeYoung
Mr. J. P. O'Reilly

8409280193 840926
PDR ADOCK 05000325
S PDR

IE22
1/0