

RECEIVED
NRC

Arizona Public Service Company

1984 NOV -5 AM 9:08

November 2, 1984
ANPP-31045-TDS/LBS

REGION V LBS

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Reactor Safety and Projects

Subject: Time Extension For Report - DER 84-53
A 50.55(e) Potentially Reportable Deficiency Relating To
Bonnet and Diaphragm Nuts And Bolts Found Loose On PC & CH
Valves.
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and T. Bradish on
August 17, 1984
(B) ANPP-30533, dated September 17, 1984 (Interim Report)


Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), and an Interim Report was transmitted by Reference (B).
At that time, it was estimated that a Final Report would be available by
November 2, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by November 16, 1984, at
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Production
ANPP Project Director

EEVB/LBS/nj

cc: See Page Two

8411200249 841102
PDR ADDCK 05000528
S PDR

1/0
IE-27

Mr. T. W. Bishop
DER 84-53
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
D. B. Karner
W. E. Ide
D. B. Fasnacht
A. C. Rogers
L. A. Souza
D. E. Fowler
T. D. Shriver
C. N. Russo
B. S. Kaplan
J. Vorees
J. R. Bynum
J. M. Allen
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
R. P. Zimmerman
L. Clyde
M. Woods
T. J. Bloom

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339