

Part 21

POWER RECTOR				EVENT NUMBER: 24032		
FACILITY: COMANCHE PEAK		REGION: 4	NOTIFICATION DATE: 08/12/92			
UNIT: [ ] [2] [ ]		STATE: TX	NOTIFICATION TIME: 15:26 [ET]			
RX TYPE: [1] W-4-LP, [2] W-4-LP			EVENT DATE: 08/12/92			
NRC NOTIFIED BY:			EVENT TIME: 00:00 [CDT]			
HQ OPS OFFICER: JEFF HAROLD			LAST UPDATE DATE: 08/12/92			
EMERGENCY CLASS: NOT APPLICABLE				NOTIFICATIONS		
10 CFR SECTION:						
GCON 50.55(e)(1)		CONSTRUCT DEFICIENCY				
CCCC 21.21		UNSPECIFIED PARAGRAPH				
UNIT	SCRAM CODE	RX CRIT	INIT PWR	INIT RX MODE	CURR PWR	CURR RX MODE
2	N	N	0	UNDER CONSTRUCT	0	UNDER CONSTRUCT

EVENT TEXT

RECEIVED FACSIMILE, LICENSEE REPORT# TSL-92115, FROM TEXAS UTILITY DOCKET #50-446, "DURING STARTUP TESTING ON JUNE 26, 1992, IT WAS DISCOVERED THAT BORE CLEARANCE IN THE UNIT 2 TRAIN "A" DIESEL GENERATOR LUBE OIL PRESSURE REGULATING VALVES ARE LESS THAN REQUIRED, CAUSING THE VALVES TO STICK OPEN. THE VALVE HOUSINGS WILL BE HONED TO PROPER DIMENSIONS ONSITE IN ACCORDANCE WITH VENDOR'S INSTRUCTIONS. ROOT CAUSE AND PREVENTIVE ACTION WILL BE DETERMINED."

140000 920812  
9208140138 920812  
PDR ADDOCK 05000446  
S PDR

JE 19 1/0