

Part 21

POWER REACTOR				EVENT NUMBER: 24033		
FACILITY: COMANCHE PEAK		REGION: 4	NOTIFICATION DATE: 08/12/92			
UNIT: [] [2] []		STATE: TX	NOTIFICATION TIME: 15:26 [ET]			
RX TYPE: [1] W-4-LP, [2] W-4-LP			EVENT DATE: 08/12/92			
NRC NOTIFIED BY:			EVENT TIME: 00:00[CDT]			
HQ OPS OFFICER: JEFF HAROLD			LAST UPDATE DATE: 08/12/92			
NOTIFICATIONS						
EMERGENCY CLASS: NOT APPLICABLE						
10 CFR SECTION:						
GCON 50.55(e)(1)		CONSTRUCT DEFICIENCY				
CCCC 21.21		UNSPECIFIED PARAGRAPH				
UNIT	SCRAM CODE	RX CRIT	INIT PWR	INIT RX MODE	CURR PWR	CURR RX MODE
2	N	N	0	UNDER CONSTRUCT	0	UNDER CONSTRUCT

EVENT TEXT

A FACSIMILE, LICENSEE REPORT#TSL-92116, WAS RECEIVED FROM TEXAS UTILITIES ELECTRIC DOCKET #50-446, "ON JUNE 29, 1992, A THIN STAINLESS STEEL BLANK WAS FOUND IN THE UNIT 2 TRAIN "B" DIESEL GENERATOR GEAR CASE LUBE OIL SUPPLY LINE. THE ENGINE WAS RUN IN THIS CONDITION FOR A TOTAL OF APPROXIMATELY 82 MINUTES AT VARIOUS RPMs AND LOAD CONDITIONS. THE BLANK WILL BE REMOVED. THE ENGINE JACKET WATER PUMP, CAM SHAFT GEAR OUTBOARD SUPPORTS, OVERSPEED GOVERNOR DRIVE, OVERSPEED GOVERNOR, AND IDLER GEAR BUSHING ASSEMBLY WILL BE INSPECTED FOR DISTORTION, DISCOLORATION, AND DAMAGE. COMPONENTS WILL BE REPLACED AS NECESSARY. ROOT CAUSE AND PREVENTATIVE ACTION WILL BE DETERMINED."

JE 19 1/0