



Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

1984 NOV 19 PM 1:16

REGION V IRE

November 16, 1984
ANPP- 31161-TDS/TRB

U. S. Nuclear Regulatory Commission
Region V
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. F. Kirsch

Subject: Time Extension For Report - DER 84-53
A 50.55(e) Potentially Reportable Deficiency Relating To
Bonnet and Diaphragm Nuts and Bolts Found Loose On PC And CH
Valves.
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and T. Bradish on
August 17, 1984
(B) ANPP-30533, dated September 17, 1984 (Interim Report)
(C) ANPP-31045, dated November 2, 1984 (Time Extension)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), an Interim Report was transmitted by Reference (B), and a
Time Extension was requested by Reference (C). At that time, it was
estimated that a Final Report would be available by November 16, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by November 29, 1984, at
which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt, Jr.
APS Vice President
Nuclear Production
ANPP Project Director

EEVB/TRB/nj

cc: See Page Two

8412010023 841116
PDR ADOCK 05000528
S PDR

1/0
IE-27

Mr. D. F. Kirsch
DER 84-53
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
D. B. Karner
W. E. Ide
D. B. Fasnacht
A. C. Rogers
L. A. Souza
D. E. Fowler
T. D. Shriver
C. N. Russo
B. S. Kaplan
J. R. Bynum
J. M. Allen
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
R. P. Zimmerman
L. Clyde
M. Woods
T. J. Bloom

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339