

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Arkansas Nuclear One - Unit 2 DOCKET NUMBER (2) PAGE (3)  
101510101 31 61 8110F11

TITLE (4) Fire Door Found Open

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names	Docket Number(s)
01	21	85	85	01	01	01	21	85		101510101
OPERATING MODE (9) 1 THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)										
POWER LEVEL (10)		20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)		
		20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)		
		20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		Other (Specify in		
		20.405(a)(1)(iii)		50.73(a)(2)(i)		50.73(a)(2)(viii)(A)		Abstract below and		
		20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)		in Text, NRC Form		
		20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)		366A)		

LICENSEE CONTACT FOR THIS LER (12)  
Name Patrick C. Rogers, Plant Licensing Engineer Telephone Number  
Area  
Code  
51011916141-1311010

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)									
Cause	System	Component	Manufacturer	Reportable to NPRDS	Cause	System	Component	Manufacturer	Reportable to NPRDS

SUPPLEMENT REPORT EXPECTED (14)  
EXPECTED SUBMISSION DATE (15) 01 09 85  
Month Day Year  
18 15 5

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 2/21/85, a fire watch was requested to be posted at fire door #206, a water-tight door to the "B" high pressure safety injection pump room, so that the door could be opened for painting and labeling as a fire door; the fire watch found the door open. The door was painted and labeled after which the door was closed. It is believed the individual who left the door open did not realize the door was a fire door since it lacked proper fire door labeling in accordance with the new fire barrier and penetration marking program. AP&L is expediting efforts to complete the fire door labeling program in order to eliminate confusion and prevent recurrence.



ARKANSAS POWER & LIGHT COMPANY

POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

March 22, 1985

2CANØ38512


U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Report  
No. 85-006-00

Gentlemen:

In accordance with 10CFR50.73(a)(2)(i), attached is the subject report concerning a fire door which was found open.

Very truly yours,



J. Ted Enos  
Manager, Licensing

JTE:RJS:ds

Attachment

cc: Mr. Richard C. DeYoung  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Norman M. Haller, Director  
Office of Management & Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

IE22  
11