

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

February 21, 1996

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Serial No. 96-027
NL/RPC
Docket Nos. 50-338
50-339
License Nos. NPF-4
NPF-7

Gentlemen:


VIRGINIA ELECTRIC AND POWER COMPANY
NORTH ANNA POWER STATION UNITS 1 AND 2
1995 ANNUAL STEAM GENERATOR INSERVICE INSPECTION REPORT

In accordance with the requirements of Technical Specifications 4.4.5.5.b and 6.9.1.4, Virginia Electric and Power Company submits the 1995 Steam Generator Inservice Inspection Report for North Anna Power Station Units 1 and 2.

North Anna Power Station Unit 1 had no scheduled outages or inservice examinations in 1995. During the March - June 1995 refueling outage for North Anna Power Station Unit 2, the steam generators were replaced. Therefore, inservice inspections were not performed during 1995.

Should you require additional information, please contact us.

Very truly yours,



M. L. Bowling, Manager
Nuclear Licensing and Operations Support

cc: U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, N.W.
Suite 2900
Atlanta, Georgia 30323

Mr. R. D. McWhorter
NRC Senior Resident Inspector
North Anna Power Station

9602260342 960221
PDR ADOCK 05000338
G PDR

600006

AC47 1/0