

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Susquehanna Steam Electric Station - Unit 2

DOCKET NUMBER (2)

0 5 0 0 0 3 8 8

PAGE (3)

1 OF 01

TITLE (4)

Fire Watch Not Performed as Required.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)								
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)						
1	2	0	6	8	4	8	4	0	2	3	0	5	0	0	0		
												0	5	0	0	0	

OPERATING MODE (9)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)																								
4	<table border="1"><tr><td>20.402(b)</td><td>20.406(e)</td><td>50.73(a)(2)(iv)</td><td>73.71(b)</td></tr><tr><td>20.406(a)(1)(i)</td><td>50.36(e)(1)</td><td>50.73(a)(2)(v)</td><td>73.71(c)</td></tr><tr><td>20.406(a)(1)(ii)</td><td>50.36(e)(2)</td><td>50.73(a)(2)(vi)</td><td>OTHER (Specify in Abstract below and in Text, NRC Form 365A)</td></tr><tr><td>20.406(a)(1)(iii)</td><td>X 50.73(a)(2)(i)</td><td>50.73(a)(2)(vii)(A)</td><td></td></tr><tr><td>20.406(a)(1)(iv)</td><td>50.73(a)(2)(ii)</td><td>50.73(a)(2)(vii)(B)</td><td></td></tr><tr><td>20.406(a)(1)(v)</td><td>50.73(a)(2)(iii)</td><td>50.73(a)(2)(ix)</td><td></td></tr></table>	20.402(b)	20.406(e)	50.73(a)(2)(iv)	73.71(b)	20.406(a)(1)(i)	50.36(e)(1)	50.73(a)(2)(v)	73.71(c)	20.406(a)(1)(ii)	50.36(e)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 365A)	20.406(a)(1)(iii)	X 50.73(a)(2)(i)	50.73(a)(2)(vii)(A)		20.406(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(vii)(B)		20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)	
20.402(b)	20.406(e)	50.73(a)(2)(iv)	73.71(b)																						
20.406(a)(1)(i)	50.36(e)(1)	50.73(a)(2)(v)	73.71(c)																						
20.406(a)(1)(ii)	50.36(e)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 365A)																						
20.406(a)(1)(iii)	X 50.73(a)(2)(i)	50.73(a)(2)(vii)(A)																							
20.406(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(vii)(B)																							
20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)																							

LICENSEE CONTACT FOR THIS LER (12)
NAME
T.P. Baileys
TELEPHONE NUMBER
AREA CODE
717 542-1324COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13):

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
A	*	*	*	NO					

SUPPLEMENTAL REPORT EXPECTED (14)
YES (If yes, complete EXPECTED SUBMISSION DATE) ☐ NO ☒
EXPECTED SUBMISSION DATE (15)
MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

A fire watch was required in one area of the plant for two independent work activities. When one work activity was completed on December 6, 1984, the fire watch for the area was removed from the fire watch log. The fire watch log did not reference the two work activities. When the error was discovered on December 17, 1984, the fire watch was reinstated.

Operations Section has developed additional guidelines for tracking fire protection LCO activities. Administrative procedure AD-QA-302, System Status and Equipment Control has been revised to provide for an individual LCO Log for fire protection related activities. The addition of this separate log is expected to reduce the possibility of administrative errors related to fire protection LCO's.

* Not Applicable.

8504090089 850404
PDR ADDCK 05000388
S PDR

IE224



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

April 4, 1985

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 84-023-01
ER 100450 FILE 841-23
PLAS - 061

Docket No. 50-388
License No. NPF-22

Attached is Licensee Event Report 84-023-01. This event was determined reportable per 10CFR50.73(a)(2)(i) in that a fire watch was not performed as required by Technical Specification Action Statement 3.7.6.4.a. during the period of December 6, 1984 to December 17, 1984. This supplement describes action taken to prevent recurrence of the event.

H. W. Keiser
Superintendent of Plant-Susquehanna

TPB/ml

Attachment

cc: Dr. Thomas E. Murley
Regional Administrator, Regional
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Mr. R. H. Jacobs
Senior Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

IE22

11