

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

NOV 30 3 P 1:22 November 28, 1984

BLRD-50-438/82-20
BLRD-50-439/82-18

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - OMISSIONS TO AUXILIARY FEEDWATER
PUMP DRAWINGS - BLRD-50-438/82-20, BLRD-50-439/82-18 - SEVENTH INTERIM
REPORT


The subject deficiency was initially reported to NRC-OIE Inspector
R. V. Crlenjak on February 25, 1983 in accordance with 10 CFR 50.55(e) as
NRC BLN BLP 8207. This was followed by our interim reports dated March 25,
July 20, September 7, and December 14, 1982, and April 6 and December 5,
1983. Below is our seventh interim report. We expect to submit our next
report by May 15, 1985.

The auxiliary feedwater pump vent, drains, and turbine cooling water
interconnecting piping analysis referenced in our sixth report has been
completed for unit 1. The unit 2 analysis is currently being reviewed.
Further information will be provided in our next report.

If you have any questions, please get in touch with R. H. Shell at FTS
858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


J. W. Huffman, Manager
Licensing and Regulations

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8412130609 841128
PDR ADOCK 05000438
S PDR