

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

November 29, 1984

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: McGuire Nuclear Station, Unit 1
Docket No. 50-369
LER 369/84-29

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), attached is Licensee Event Report 369/84-29 concerning a high concentration of nitrogen in the upper head injection (UHI) water accumulator, in excess of technical specification limits, which is submitted in accordance with §50.73(a)(2)(i). This event was considered to be of no significance with respect to the health and safety of the public.

As noted in the body of the report, this event lead to the discovery of improperly installed UHI level instrumentation. The report on that is scheduled to be submitted by December 7, 1984. Also under development is a comprehensive corrective action plan intended to preclude events of this nature from future occurrence. This plan will be submitted when finalized.

Very truly yours,

H.B. Tucker

Hal B. Tucker
SAG:glb

Attachment

cc: Mr. James P. O'Reilly
Regional Administrator
U. S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, GA 30323

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington, Suite 245
Farmington, CT 06032

8412170158 841129
PDR ADOCK 05000369
S PDR

IE22
1/1