

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) EDWIN I. HATCH, UNIT I										DOCKET NUMBER (2) 0 5 0 0 0 3 2 1 1					PAGE (3) 1 OF 0 2												
TITLE (4) Spurious Reactor Protection System Logic Actuation																											
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)														
1	1	1	4	8	4	8	4	0	1	2	0	0	1	2	1	4	8	4	0	5	0	0	0				
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																									
5		20.402(b)				20.406(c)				<input checked="" type="checkbox"/> 50.73(a)(2)(iv)				73.71(b)													
POWER LEVEL (10)		20.406(a)(1)(i)				50.36(c)(1)				50.73(a)(2)(v)				73.71(c)													
0 0 0		20.406(a)(1)(ii)				50.36(c)(2)				50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 365A)													
		20.406(a)(1)(iii)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(A)																	
		20.406(a)(1)(iv)				50.73(a)(2)(iii)				50.73(a)(2)(viii)(B)																	
		20.406(a)(1)(v)				50.73(a)(2)(iv)				50.73(a)(2)(ix)																	
LICENSEE CONTACT FOR THIS LER (12)																											
NAME										TELEPHONE NUMBER																	
T. L. Elton, Acting Superintendent of Regulatory Compliance										9 1 1 2 3 1 6 1 7 1 7 8 1 5 1 1																	
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC																	
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)			MONTH	DAY	YEAR												
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)										<input checked="" type="checkbox"/> NO																	

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 11/14/84, at approximately 0810 CST, and on 11/20/84 at approximately 0747 CST, RPS logic actuations occurred for no apparent reason.

Further investigation of each of the above events has revealed no cause.

8412200329 841214
PDR ADOCK 05000321
S PDR

IF 22
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85


FACILITY NAME (1) EDWIN I. HATCH, UNIT I	DOCKET NUMBER (2) 0500032184	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		012	00	02	02	00	02

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On 11/14/84, at approximately 0810 CST, and on 11/20/84 at approximately 0747 CST, and with the unit shutdown for a refueling outage with no fuel in the reactor, RPS logic actuations occurred for no apparent reason. Since RPS is an ESF, these events are being reported as required by 10CFR50.73(a)(2)(iv).

Further investigation for each of the above events has revealed no cause.

Georgia Power Company
Post Office Box 439
Baxley, Georgia 31513
Telephone 912 367-7781
912 537-9444




Edwin I. Hatch Nuclear Plant

December 14, 1984
M-84-1121

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-321

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attached is Licensee Event Report No. 50-321/1984-012. This report is required by 10CFR 50.73(a)(2)(iv).



H. C. Nix
General Manager

JCC
HCN/TLE/vlz

xc: R. J. Kelly
R. E. Conway
J. T. Beckham, Jr.
P. D. Rice
K. M. Gillespie
Superintendent of Regulatory Compliance
R. D. Baker
Control Room
Document Control

IE22
1/1