

# WOLF CREEK

NUCLEAR OPERATING CORPORATION

Otto L. Maynard  
Vice President Plant Operations

March 13, 1996

WC 96-0042

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Mail Station P1-137  
Washington, D. C.

Subject: Docket 50-482: Special Report 96-001 - Steam Generator  
Tube Plugging Report

Gentlemen:

This letter provides information regarding the number of tubes plugged in each steam generator as required by Wolf Creek Generating Station Technical Specification 4.4.5.5. This technical specification requires, in part, that the number of tubes plugged in each steam generator be reported to the Nuclear Regulatory Commission within 15 days following the completion of each inservice inspection of the steam generator tubes.

The inservice inspection of Steam Generators "B" and "C" was completed March 5, 1996. This inservice inspection resulted in mechanical plugging of 12 tubes in Steam Generator "B" and four tubes in Steam Generator "C." Mechanical plugging was necessary because of indications of anti-vibration bar wear found during the inservice inspection.

If you have any questions concerning this matter, please contact me at (316) 364-8831 extension 4450, or Mr. Richard D. Flannigan at extension 4500.

Very truly yours



Otto L. Maynard

190013

OLM/jra

cc: L. J. Callan (NRC)  
W. D. Johnson (NRC)  
J. F. Ringwald (NRC)  
J. C. Stone (NRC)

9603200179 960313  
PDR ADOCK 05000482  
Q PDR

P.O. Box 411 / Burlington, KS 66839 / Phone: (316) 364-8831

An Equal Opportunity Employer M/F/HC/VET

A001  
1/0