



BOSTON EDISON

Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360

Roy A. Anderson

Senior Vice President - Nuclear


June 17, 1992
BECO 92-064

Mr. Paul D. Krauss
Wiss, Janney, Elstner Associates, Inc.
330 Pfingsten Road
Northbrook, IL 60062-2095

License DPR-35
Docket 50-293

Subject: SURVEY OF DETERIORATION AND REPAIR OF
CONCRETE IN NUCLEAR POWER FACILITIES

In response to the NRC letter on the captioned subject dated March 11, 1992, we are enclosing a completed survey for Pilgrim Station repair of concrete. In instances where no response is provided, we are unaware of any problems or repairs in these areas; however, we have not thoroughly researched Pilgrim's history. Furthermore, we request that the information contained in the survey be handled in a confidential manner as stated on page 2, paragraph 4, of the NRC letter.


R. A. Anderson

MTL/prochgem
Enclosure

cc: See page 2

220137
9206240225 920617
PDR ADDCK 05000293
P PDR

AP01
11

BOSTON EDISON COMPANY

DATE: June 17, 1992

PAGE 2

cc: Mr. R. Eaton
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation
Mail Stop: 1401
U. S. Nuclear Regulatory Commission
1 White Flint North
11555 Rockville Pike
Rockville, MD 20852

U. S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406

Senior NRC Resident Inspector
Pilgrim Nuclear Power Station

U. S. Nuclear Regulatory Commission ✓
Document Control Desk
Washington, DC 20555