

MIDDLE SOUTH
UTILITIES SYSTEM


**LOUISIANA
POWER & LIGHT**

142 DELARONDE STREET • P.O. BOX 8008
NEW ORLEANS, LOUISIANA 70174-8008 • (504) 366-2345

December 19, 1984

W3P84-3472
Q-3-A35.07
3-A1.01.04
A4.05

Mr. R. D. Martin
Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011



Dear Mr. Martin:

Subject: Waterford 3 SES
Docket No. 50-382
Potentially Reportable Deficiency No. 180
"Failure to Maintain Adequate Document Control
of Vendor Manuals"

- References: 1. W3P84-3221 from K.W. Cook (LP&L) to J.T. Collins (NRC),
dated 11/16/84
2. W3P84-2386 from K.W. Cook (LP&L) to J.T. Collins (NRC),
dated 9/13/84

In accordance with 10CFR50.55(e), LP&L provided telephone notification on September 18, 1984 of the subject deficiency. Via Reference 1, LP&L obtained an extension to December 17, 1984 for submittal of the written report on PRD-180. The Reference 2 letter provided LP&L's response to related Violation No. 8425-01 which provided details on corrective actions planned and underway to resolve this violation.

LP&L requires additional time to evaluate the safety significance of PRD-180 for reportability determination of the deficiency per 10CFR50.55(e) guidance. LP&L has, therefore, rescheduled the submittal of the written report on PRD-180 for January 16, 1985.

If you have any questions, please contact Mr. G. E. Wuller at (504) 464-3499, Onsite Licensing.

Yours very truly,

K.W. Cook

K.W. Cook
Nuclear Support & Licensing Manager

KWC:GEW:sms

cc: NRC, Director, Office of I&E
G.W. Knighton, NRC-NRR
J.H. Wilson, NRC-NRR
NRC Resident Inspectors Office

INPO Records Center
(Attn: D.L. Gillispie)
E.L. Blake
W.M. Stevenson

8501020279 841219
PDR ADOCK 05000382
S PDR

IE-27.10