

DMB

ILLINOIS POWER COMPANY



1A.120
U-10245
CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 31727

January 31, 1985

Docket No. 50-461

Mr. James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Potential 10CFR Part 21 Defect in Titus Model 272
Grilles at Clinton Power Station (21-85-01)

Dear Mr. Keppler:

In Illinois Power Company's letter to Frank Jablonski, NRC Region III, (Ref. U-10021, 1606-L, dated January 17, 1983), Illinois Power agreed to notify Region III of those 10CFR Part 21 defects that affect Clinton Power Station and that were previously reported to the Commission by vendors or contractors. In accordance with this agreement, the following information is submitted:

Titus Products has notified the USNRC of a potential 10CFR21 defect (Internal tension wires used for adjustment of the blades will not remain in place when the blades are closed.) that exists in their Model 272 Grilles.

Titus Products is presently conducting tests to identify rework methods and procedures. Upon completion they will schedule personnel to correct this deficiency. Illinois Power is also conducting an evaluation of this condition and will assure that adequate corrective action is taken. Documentation of this potential problem and the corrective action taken will be available for your review at our offices.

Sincerely yours,

D. P. Hall
Vice President

JV/lr (NRCL)

cc: NRC Resident Office
Illinois Department of Nuclear Safety
Director, Office of I&E, USNRC, Washington, D. C. 20555
INPO Records Center

8502080374 850131
PDR ADOCK 05000461
S PDR

FEB 6 1985

10 IE 19