

Dear Judge Hoyt, here is an updated list of inspection reports and deficiencies. I repeat that these reports mirror a continuing problem on the sight with contruaction and quality.

INFORMATION FROM INSPECTION REPORTS

M. I. LEWIS  
6504 BRADFORD TERR.  
PHILA., PA. 19149

<u>Report number</u>	<u>Violation</u>	<u>Unresolved items</u>	<u>Open issues</u>	<u>Other</u>
50-352/84-59				discrepancies
84-60 and 84-13				procedures not revised
84-55		x		
84-51			x	
84-56		x		
84-58				
84-50				followup needed
84-49 and 84-12	x			fuel rod procedure not ok'd.
84-46		x		
84-42		x		
84-47		x		
84-29	x	x	x	deficiencies and unacceptable
84-44				test exception
84-27	4	x		
84-33			x	construction deficiency
84-31		x		
84-41				many deficiencies
84331			x	confusin g writing
84-36 and 353/84-10		x	x	
84-34				teshchange notice (TCN)
84-16				lack of commucination btn shifts.
84-35			x	
84-26 and 353 /84-09	2			
Board Notification 84-142	Pipeline hazards			
84-30				

Please note that this list only contains letters from NRC to Peco for the months of August, September, October and November. There are issues still being generated and there are issues still open from months and years previous to the letters in the above list. Also the list does not demonstrate all deficiencies in these letters.

850208039B 850207  
PDR ADOCK 05000352  
G PDR

SERVED FEB 7 1985

M. I. LEWIS  
6504 BRADFORD TERR.  
PHILA., PA. 19149

ONCKET NUMBER  
PROD. & UTIL. PA...

50-352-02  
30-35-300

ONCKET  
USNR

85  
FEB-7 1985  
19:16  
RECEIVED  
SEARCH & SEIZURE  
DIVISION