

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

84 SEP 18 13:29
September 12, 1984

TELEPHONE
(704) 373-4531

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Re: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
IE Bulletin 84-02

Dear Sir:

This letter is a Supplemental response to IE Bulletin 84-02 which concerns failures of GE type HFA relays in use in class IE Safety Systems. By a letter dated July 13, 1984, Duke provided an initial response to this Bulletin for Oconee Nuclear Station. In this letter you were informed that Duke's review addressing the generic concerns expressed in the Bulletin was still in progress and would be provided shortly after completion of the investigation. This letter provides the results of our investigation.

Duke has found that there are no similar problems with Oconee's safety-related relays.

I declare under penalty of perjury that the information contained herein is correct to the best of my knowledge as executed on September 12, 1984.

Very truly yours,



Hal B. Tucker

PFG:slb

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. J. C. Bryant
NRC Resident Inspector
Oconee Nuclear Station

Ms. Helen Nicolaras
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8410310717 840912
PDR ADOCK 05000269
Q PDR

IE1110