

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Prairie Island Unit 1										DOCKET NUMBER (2) 0 5 0 0 0 2 8 2				PAGE (3) 1 OF 0 2		
TITLE (4) One main steam safety valve setpoint found out of spec																
EVENT DATE (6)			LER NUMBER (8)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (9)						
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)			
0 1	1 2	8 5	8 5	0 0 2	0 0	0 2	1 1	8 5					0 5 0 0 0			
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)														
N		20.402(b)				20.406(a)				80.73(a)(2)(iv)				73.71(b)		
POWER LEVEL (10)		20.406(a)(1)(i)				80.36(a)(1)				80.73(a)(2)(v)				73.71(a)		
0 0 0		20.406(a)(1)(ii)				80.36(a)(2)				80.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)		
		20.406(a)(1)(iii)				80.73(a)(2)(i)				80.73(a)(2)(viii)(A)						
		20.406(a)(1)(iv)				80.73(a)(2)(ii)				80.73(a)(2)(viii)(B)						
		20.406(a)(1)(v)				80.73(a)(2)(iii)				80.73(a)(2)(ix)						
LICENSEE CONTACT FOR THIS LER (12)																
NAME Arne A. Hunstad, Staff Engineer										TELEPHONE NUMBER						
										AREA CODE 6 1 2 3 8 8 - 1 1 2 1						
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC						
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)												NO		0 3	1 5	8 5
ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)																

During surveillance test at shutdown for refueling, one of ten main steam safety valves failed to open at its setpoint. A supplemental report will be made.

8502150484 850211  
PDR ADOCK 05000282  
S PDR

IE22  
1/1

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Prairie Island Unit 1	0 5 0 0 0 2 8 2	8 5	— 0 0 2	— 0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On January 12th, Unit 1 was shutdown for refueling. During a surveillance test, one of the ten main steam (SB) safety valves (V) failed to open at its setpoint. Cause has not yet been determined since repairs have not been made. The valve will be made operable before restart and a supplemental report will be made.



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

February 11, 1985

U S Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-282 License No. DPR-42

One Main Steam Safety Valve Stepout  
Found Out of Spec

The License Event Report for this occurrence is attached.

This event was reported via Emergency Notification System per 10 CFR Part 72  
on January 12, 1985.

*Eugene Eckhardt*

for David Musolf  
Manager - Nuclear Support Services

DMM/EFE/dab

c: Regional Administrator-III, NRC  
NRR Project Manager, NRC  
Resident Inspector, NRC  
MPCA  
Attn: J W Ferman

Attachment

IF22  
11