



Northern States Power Company

Prairie Island Nuclear Generating Plant

1717 Wakonade Dr. East
Welch, Minnesota 55089

April 12, 1996

10 CFR Part 50
Section 50.73

U S Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT

Docket Nos. 50-282 License Nos. DPR-42
50-306 DPR-60

Degraded Steam Generator Tube Sleeves

The Licensee Event Report for this occurrence is attached. In the report, we made no new NRC commitments. We earlier made commitments regarding the sleeve problems in our letter to the Commission dated February 28, 1996. Further commitments may be contained in future licensing submittals (we expect to submit a request for a License Amendment for the use of these sleeves).

Detailed metallurgical analysis will be contained in our letter submitting the 90-day ISI report for the refueling outage.

This event was reported via the Emergency Notification System in accordance with 10 CFR Part 50, Section 50.72, on March 13, 1996 and March 17, 1996. Please contact us if you require additional information related to this event.

Michael D Wadley
Plant Manager
Prairie Island Nuclear Generating Plant

c: Regional Administrator - Region III, NRC
NRR Project Manager, NRC
Senior Resident Inspector, NRC
Kris Sanda, State of Minnesota

Attachment

160019

9604170114 960412
PDR ADOCK 05000282
S PDR