

Swagelok

CRAWFORD FITTING COMPANY
OLON, OHIO 44139

FRED A. LENNON
CHAIRMAN

PHONE (216) 248-4600
FAX (216) 349-5970

May 30, 1996

Document Control Desk
Office of Nuclear Reactor Regulation
Nuclear Regulatory Commission
Washington, DC 20555

Subject: Defects Potentially Reportable Under 10CFR21

Gentlemen:

Further to our letters of February 26th and April 3rd, 1996 we are writing about a possible material defect in certain stainless steel Swagelok tube fittings.

Enclosed is a list of three additional shipments to a nuclear facility of parts that are included in this investigation. This is the same potential defect and same part numbers discussed in our previous letters.

All three shipments were to Duquesne Light's Beaver Valley Station.

We have already notified the facility about this potential problem.

If you have any questions, please do not hesitate to contact us.

Sincerely,



David J. Johnston
V.P. and General Manager

030110

rdk

cc: WRC
EPM
EDS

9606040012 960531
PDR ADDCK 05000334
S PDR

IF19
11

	<u>Qty.</u>	<u>Part No.</u>	<u>Heat Code</u>
Duquesne Light Beaver Valley Station P.O. D106368, R199 I.D. R15JS0513B	25 pcs.	SS-810-3	HHT
P.O. D106368, R194 I.D. R15FC0522B	30 pcs.	SS-400-9	GCZ
P.O. D106368, R195 I.D. R15JD0502B	10 pcs.	SS-400-2-4	HDR