

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

85 MAR 27 8 57
March 25, 1985

BLRD-50-438/84-50
BLRD-50-439/84-46

U.S. Nuclear Regulatory Commission
Region II
Attn: Dr. J. Nelson Grace, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Dr. Grace:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - UNAUTHORIZED SUBSTITUTION OF
UNISTRUT ATTACHMENTS FOR SSDs - BLRD-50-438/84-50, BLRD-50-439/84-46 -
SUPPLEMENTAL FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
P. E. Fredrickson on September 17, 1984 in accordance with 10 CFR 50.55(e)
as NCR 3436. Our first interim report was submitted on October 12, 1984
and our final report on February 13, 1985. Below is our supplement to our
final report.

The date of February 17, 1985 for completion of corrective actions
indicated in our final report on this matter was not met. TVA approved the
revised anchor substitution criteria on an interim basis via the field
change request (FCR) process to expedite implementation. The FCR's paper
work required has delayed issuance of the official design drawings. The
corrective action on this matter will be completed by April 15, 1985.

If you have any questions, please get in touch with R. H. Shell at
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. W. Hufham

J. W. Hufham, Manager
Licensing and Regulations

cc: Mr. James Taylor, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8505010636 850325
PDR ADJCK 05000438
S PDR

An Equal Opportunity Employer

IE 27
111