

Georgia Power Company  
40 Inverness Center Parkway  
Post Office Box 1295  
Gwinnett Co., Alabama 35201  
Telephone 205 877-7122

C. K. McCoy  
Vice President, Nuclear  
Vogtle Project



November 5, 1992

MSV-01136  
#3603

Docket No. 50-424

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555

Gentlemen:

VOGTLE ELECTRIC GENERATING PLANT  
CORRECTION TO INSERVICE INSPECTION SUMMARY REPORT

By letter MSV-00876 dated February 13, 1992, Georgia Power Company (GPC) submitted Volumes 1 and 2 of the Vogtle Electric Generating Plant, Unit 1 (VEGP-1) Inservice Inspection (ISI) Final Report which discussed ISI activities conducted at VEGP-1 during the Fall 1991 maintenance/refueling outage. Those report volumes constituted the "Owner's Report for Inservice Inspection (Form NIS-1)" required by Subsubarticle IWA-6230 of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code, Section XI, 1983 Edition with Addenda through Summer 1983.

During the course of preparing the ISI Final Report document for ISI activities conducted at Unit 2 (VEGP-2), it was noted that certain examinations which were performed during the VEGP-1 Fall 1991 maintenance/refueling outage had not been addressed in the ISI Final Report for VEGP-1. Similar examinations were performed at VEGP-2 during the Spring 1992 maintenance/refueling outage and were addressed in the VEGP-2 ISI Final Report for that outage. Specifically, the surface examination of four 2-inch thermowell-to-branch connection welds were inadvertently omitted from the VEGP-1 ISI Final Report. The subject welds resulted from a piping modification which was performed during the VEGP-1 Fall 1991 maintenance/refueling outage on the RTD section of the Reactor Coolant System. The examination results for each of the thermowell-to-branch connection welds were satisfactory.

Enclosed are corrected pages which are to be incorporated into Volume 1 of the report submitted by our February 13, 1992 letter. Instructions for incorporating the corrected pages are provided in the enclosure. Corrections to the report are denoted by marginal lines.

9211160103 921105  
PDR ADDCK 05000424  
Q PDR


ACH 7

U. S. Nuclear Regulatory Commission  
MSV-01136  
Page Two

Five copies of the corrections to Volume 1 of the ISI Final Report for the VEGP-1 Fall 1991 maintenance/refueling outage are provided for your use. Two copies of the corrections to the subject report volume are being provided to the Regional Administrator for USNRC Region II.

Should there be any questions in this regard, please contact this office.

Sincerely,

  
C. K. McCoy

CKM/JAE/jae

Enclosure: Correction to VEGP-1 ISI Final Report for Fall 1991  
Maintenance/Refueling Outage

xc: Georgia Power Company  
Mr. S. H. Chesnut  
Mr. M. Sheibani  
Mr. W. B. Shipman  
NORMS

U. S. Nuclear Regulatory Commission  
Mr. S. D. Ebnetter, Regional Administrator  
Mr. D. S. Hood, Licensing Project Manager, NRR  
Mr. B. R. Bonser, Senior Resident Inspector, Vogtle