

**PERRY NUCLEAR POWER PLANT**

10 CENTER ROAD
PERRY, OHIO 44081
(216) 259-3737

Mail Address:
P.O. BOX 87
PERRY, OHIO 44081

Donald C. Shelton
SENIOR VICE PRESIDENT
NUCLEAR

August 8, 1996
PY-CBI/NRR-2087L

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Perry Nuclear Power Plant
Docket No. 50-440
10CFR50.54(a)(3) Experience Requirements of the Perry Nuclear Assurance
Department Director Position, Request for Supplemental Information

Gentlemen:

In letter PY-CBI/NRR-2078L dated July 23, 1996, the Perry Nuclear Power Plant (PNPP) requested, under provisions of 10CFR50.54(a), a one-time deviation to the Director, Perry Nuclear Assurance Department (PNAD) quality assurance experience requirements. On August 7, during a telephone conference between Mr. R. Langstaff (Nuclear Regulatory Commission Region III) and Mr. H. Coon (PNPP), Mr. Langstaff requested a copy of the proposed Updated Final Safety Analysis Report pages associated with the deviation request. Attachment 1 provides this information.

If you have questions or require additional information, please contact Mr. James D. Kloosterman, Manager - Regulatory Affairs at (216) 260-5833.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'D. Shelton'.

for Donald C. Shelton

JEE:sc

Attachment

cc: NRC Region III Administrator
NRC Resident Inspector
NRC Project Manager

Operating Companies
Cleveland Electric Illuminating
Toledo Edison

9608130119 960809
PDR ADOCK 05000440
K PDR

PY-CEI/NRR-2087L

Attachment

Page 1 of 4

- j. Provide for QA review and concurrence of safety-related plant modification and maintenance work authorizations. This includes the review of associated design documents to ensure proper review and approval, and inclusion of necessary quality assurance requirements.
- k. Provide for QA review and approval of procurement documents generated for the acquisition of materials and services that fall within the scope of this document.
- l. Provide for and maintain Quality Assurance records generated by PNAD until such time as they are turned over for permanent storage.
- m. Periodically evaluate and report on the status and adequacy of the Quality Assurance Program to appropriate management.
- n. Perform receiving inspection activities at the plant site.
- o. Provide for adequate levels of inspection and surveillance of plant activities.
- p. Provide the resources necessary to ensure that the Independent Safety Engineering Group can perform the activities described in Appendix 1A, Item I.B.1.2 and Section 13.4.3.
- q. Provide general and procedural administrative services, document control, and records management.

Qualification requirements for the Director, PNAD, at the time are:

- a. Management experience through progressive assignment of increasing responsibility.
- b. Formal degree in a science or engineering discipline or professional registration or equivalent.

PY-CEI/NRR-2087L

Attachment

Page 2 of 4

- c. Six years experience in the field of quality assurance or related activity in design, construction or operation of power plants. At least 1 year of this 6 years experience shall be nuclear power

PY-CEI/NRR-2087L

Attachment

Page 3 of 4

Insert A

plant experience in the overall implementation of the Quality Assurance Program. A minimum of 1 year of this 6 years experience shall be related technical or academic training. A maximum of 4 years experience may be fulfilled by related technical or academic training.

d. Training in QA policies, standards, regulations, and practices.

The Director, PNAD, is assisted in carrying out his responsibilities by a staff organized into sections to provide adequate coverage of procurement, manufacturing, inservice inspection, refueling, maintenance, repair, modification, and operation of Perry (Figure 17.2-2). The staff includes required expertise to perform audit, quality engineering, surveillance, and inspection functions. In addition, quality assurance agents may be engaged to augment the PNAD staff. PNAD shall maintain direct control over any quality assurance agent.

17.2.1.3.2.2.1 Manager, Quality Assurance Section

The Manager, Quality Assurance Section, is responsible for implementing a system of planned periodic internal audits and surveillances. Section activities include input to and review of procedures and corrective action programs; reviewing changes to the Operations QA Plan; surveillance of plant operations; and providing administrative support for PNAD.

17.2.1.3.2.2.2 Manager, Quality Control Section

The Manager, Quality Control Section, is responsible for review and approval of procurement documents; maintains a program for approval, audit and surveillance of suppliers; and

PY-CEI/NRR-2087L

Attachment

Page 4 of 4

Insert A

A one-time deviation to the quality assurance experience requirement was requested from the NRC by letter PY-CEI/NRR-2078L dated July 23, 1996. This request was approved by the NRC as documented in letter PY-NRR/CEI-XXXXL dated XXXX, 1996.