

Entergy Operations, Inc.
River Bend Station
5485 U. S. Highway 61
P.O. Box 220
St. Francisville, LA 70775
Tel 504 336 6225
Fax 504 635 5068

Rick J. King
Director
Nuclear Safety & Regulatory Affairs

August 12, 1996

U. S. Nuclear Regulatory Commission
Document Control Desk
Mail Stop P1-37
Washington, DC 20555

Subject: River Bend Station - Unit 1
Docket No. 50-458
License No. NPF-47
50.59 Summary Report

File Nos.: G9.5, G9.25.1.5

RBG-43153
RBF1-96-0315

Ladies and Gentlemen:

Pursuant 10CFR50.59(b)(2), Entergy Operations, Inc. (EOI) herein submits the 50.59 Summary Report that contains a brief description of changes to the facility and procedures as described in the Safety Analysis Report (SAR), and tests and experiments not described in the SAR but conducted since our last submittal. The Summary Report also contains a summary of each respective safety evaluation performed. The safety evaluations included in this report were performed in accordance with 10CFR50.59 and determined that none of the changes resulted in an unreviewed safety question.

The Summary Report is submitted in support of the Updated Final Safety Analysis Report (USAR) changes made pursuant 10CFR50.71 (e) by providing a description of all 50.59 safety evaluations performed either in support of requested license amendments or in support of conclusions that changes did not involve an unreviewed safety question. The Summary Report is also provided to meet the requirements of 10CFR50.71(e)(2)(ii) for identification of changes made under the provisions of 10CFR50.59 but not previously submitted to the Commission. Revision 8 changes to the USAR were submitted August 8, 1996, see RBG-43141. This Summary Report is submitted within six months following Refueling (RF) Outage 6 and describes changes made during the period July 6, 1994, through RF-6 (or through February 13, 1996).


9608190155 960812
PDR ADDCK 05000458
R PDR

LEA7
11

50.59 Summary Report
August 12, 1996
RBG-43153
RBF1-96-0315
Page 2 of 2

Should you have any questions, please advise Mr. T. W. Gates of my staff at (504) 381-4866.

Sincerely,

A handwritten signature in cursive script, appearing to read "R. J. King".

RJK/TWG/JHM/kvm

Attachment: 50.59 Summary Report dated August 1996

xc: U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

U. S. Nuclear Regulatory Commission
Senior Resident Inspector
P. O. Box 1050
St. Francisville, LA 70775