

April 18, 1985
(NMP2L 0389)

Mr. R. W. Starostecki, Director
U. S. Nuclear Regulatory Commission
Region I
Division of Reactor Projects
631 Park Avenue
King of Prussia, PA 19406

Re: Nine Mile Point Unit 2
Docket No. 50-410

Dear Mr. Starostecki:

Enclosed is an interim report in accordance with 10CFR50.55(e) for the problem concerning the material supplied by Northern Steel Corporation. This problem was reported via tel-con to W. Lazarus of your staff on March 19, 1985.

Very truly yours,

C. V. Mangan

C. V. Mangan
Vice President
Nuclear Engineering and Licensing

xc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

R. A. Gramm, NRC Senior Resident Inspector

Project File (2)

8505060219 850418
PDR ADDCK 05000410
S PDR

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
DOCKET NO. 50-410

Interim Report for a Problem
Concerning Material Supplied by
Northern Steel Corporation
(55(e)-85-10)

Description of the Problem:

An audit of Northern Steel Corporation indicated that some of the material supplied to Nine Mile Point - Unit 2 was purchased by Northern Steel from suppliers who did not have a Quality Assurance Program meeting the applicable requirements of 10CFR50, Appendix B. These suppliers were Ernst Steel Company of Buffalo, New York, and Alliance Fastner Company of Syracuse, New York.

A list of affected material/components was supplied by Northern Steel Company and is documented in Nonconformance and Disposition Report Nos. Z118 and Z119.

The matter is still under investigation and a final report will be submitted by June 30, 1985.