



231 W Michigan, PO Box 2046, Milwaukee, WI 53201

(414) 221-2345

VPNPD-92-351

NRC-92- 132

November 13, 1992

Document Control Desk
U.S. NUCLEAR REGULATORY COMMISSION
Mail Station P1-137
Washington, DC 20555

Gentlemen:

DOCKET 50-301

LICENSEE EVENT REPORT 92-005-00

STEAM GENERATOR TUBE DEGRADATION

POINT BEACH NUCLEAR PLANT, UNIT 2

Enclosed is Licensee Event Report (LER) 92-005-00 for Point Beach Nuclear Plant (PBNP), Unit 2. This report is provided in accordance with PBNP Technical Specification 15.4.2.A.7(a), "After each inservice inspection, the number of tubes plugged or repaired in each steam generator shall be reported to the Commission as soon as practicable," and PBNP Technical Specification 15.4.2.A.7(c), "Reports required by Table 15.4.2-1, 'Steam Generator Tube Inspection,' shall provide the information required by Technical Specification 15.4.2.A.7(b) and a description of investigations conducted to determine the cause of the tube degradation and corrective actions taken to prevent recurrence." LER 92-005-00 is filed according to Technical Specification Table 15.4.2-1 under the reporting requirement of 10 CFR 50.73(a)(2)(ii), "The licensee shall report...any event or condition that resulted in the condition of the nuclear power plant, including its principal safety barriers, being seriously degraded..."

Please contact us if any further information is required.

Sincerely,

A handwritten signature in dark ink, appearing to read 'Bob Link'.

Bob Link
Vice President
Nuclear Power

200101

DAW/jg
Enclosure

cc: NRC Resident Inspector
NRC Regional Administrator

9211230041 921113
PDR ADOCK 05000301
S PDR

A subsidiary of Wisconsin Energy Corporation

IFED
11