



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401-1927  
Telephone (612) 330-5500

November 17, 1992

Report Required by  
10 CFR Part 50, Section 50.73

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-263 License No. DPR-22

Missed Surveillance Requirement Caused by Failure to Include  
Emergency Service Water Valves in Section XI Testing Program

The supplemental Licensee Event Report for this occurrence is attached. Information learned during the investigation of a subsequent event (Licensee Event Report 92-012-00) led us to review the root cause of Licensee Event Report 92-010-00. As a result of this review, the root cause of the first event has been modified and other portions of the report have been revised accordingly.

Please contact us if you require further information.

Thomas M. Parker  
Manager  
Nuclear Support Services

c. Regional Administrator - III NRC  
Sr Resident Inspector, NRC  
NRR Project Manager, NRC  
State of Minnesota,  
Attn: Kris Sanda

Attachment

230097

9211230219 921117  
PDR ADOCK 05000263  
S PDR

IF22  
111