

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

April 30, 1985

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: Oconee Nuclear Station, Unit 1
Docket No. 50-269
LER 269/84-07

Gentlemen:

By letter dated January 2, 1985, Duke submitted Licensee Event Report 269/84-07 concerning an incident in which Oconee 1 Reactor tripped upon the loss of the Main Feedwater Pump. One of the corrective actions committed to in the report was an inspection and evaluation of the Auxiliary Oil Pump for the "2A" Main Feedwater Pump Turbine during the next Unit 2 outage.

Reliability of the Auxiliary Oil Pumps has been evaluated by the manufacturer, Design Engineering and Station Maintenance personnel. Based on this evaluation, it is felt that no inspection of the Unit 2 pump during the outage is warranted; therefore, Duke is deleting this commitment.

Very truly yours,

H.B. Tucker / HBT

Hal B. Tucker

SGG:slb

cc: Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Ms. Helen Nicolaras
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

8505070447 850430
PDR ADOCK 05000269
S PDR

*IE22
1/0*

Document Control Desk
April 30, 1985
Page Two

cc: INPC Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Mr. J. C. Bryant
NRC Senior Resident Inspector
Oconee Nuclear Station

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, New York 10020