



Public Service Electric and Gas Company P.O. Box 236 Hancocks Bridge, New Jersey 08038-0236

Nuclear Business Unit

AUG 16 1996

LR-N96259

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Dear Sir:

HOPE CREEK GENERATING STATION
DOCKET NO. 50-354
UNIT 1
LICENSEE EVENT REPORT 95-033-09

This Licensee Event Report entitled "Technical Specification Surveillance Requirement Implementation Deficiencies" is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(i)(B).

This supplement documents the discovery of a Technical Specification surveillance implementation deficiency identified by the Technical Specification Surveillance Improvement Program (TSSIP). As stated in LER 95-033-01, additional Technical Specification surveillance implementation deficiencies discovered by TSSIP with minimal safety significance will be documented in supplements to this LER on a periodic basis until completion of the TSSIP project.

Sincerely,

Mark Bezilla
General Manager -
Hope Creek Operations

9608260164 960816
PDR ADOCK 05000354
S PDR

Attachment LER

LMK/tcp
SORC Mtg. 96-078

C Distribution
LER File

230055

The power is in your hands.

1/1
Jerr