

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)										DOCKET NUMBER (2)					PAGE (3)	
Sequoyah, Unit 1										0 5 0 0 0 3 2 7 1					OF 0 2	

TITLE (4)

Failure To Comply With One-hour Fire Watch

EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																	
MONTH	DAY	YEAR	YEAR		SEQUENTIAL NUMBER		REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES					DOCKET NUMBER(S)											
0	4	0	4	8	5	-	0	1	5	-	0	0	0	5	0	2	8	5	0	5	0	0	0				
																			0	5	0	0	0				

OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)									
1		20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)			
POWER LEVEL (10)	1 0 0	20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(v)		73.71(c)			
		20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)	XX	OTHER (Specify in Abstract below and in Text, NRC Form 366A)			
		20.405(a)(1)(iii)	XX	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)					
		20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)					
		20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(ix)					
									Special Report		

LICENSEE CONTACT FOR THIS LER (12)																				
NAME										TELEPHONE NUMBER										
										AREA CODE										
David P. Ormsby, Compliance Section Engineer										6	1	5	8	7	0	-	6	1	4	6

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NPRDS	

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

An hourly fire watch was not performed within one hour due to inoperable doors. The fire watch was reestablished as soon as the door was repaired. This condition is reportable per 10 CFR 50.73 a.2.i and the special report requirements of Technical Specification 3.7.12. There was no effect upon public health or safety.

8505090089 850502
PDR ADOCK 05000327
S PDR

IE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104
EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Sequoyah, Unit 1	0 5 0 0 0 3 2 7	8 5	0 1 5	0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The event described in this report occurred while Unit 1 was in mode 1 (100 percent power, 2235 psig, 578 degrees F). This event involved a missed fire watch due to equipment failure.

At 1800 CST on April 4, 1985, the hourly fire watch for the Unit 1 Auxiliary Building Supply Air Fan Room could not be conducted because door A-123 would not open. It was found that the pin that secures the lower dogging pin to the dogging pin release rod had come out. The securing pin was reinstalled and a post maintenance check was made to verify operability of the door. The hourly fire watch was resumed at 2300 CST.

Fire watches were reestablished as soon as possible after the problem was found and repaired, although some hourly fire watches were not performed. The door failed in a closed locked condition which assured operability as a fire barrier. These events are reportable per 10 CFR 50.73 a.2.i and the special report requirements of Technical Specification 3.7.12. There was no effect on public health or safety.

Previous occurrences - six (SQRO-50-327/85013, 85012, 85011, 85008, 85003, and 84075).

TENNESSEE VALLEY AUTHORITY

Sequoyah Nuclear Plant
Post Office Box 2000
Soddy Daisy, Tennessee 37379

May 2, 1985

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO.
50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT
SQRO-50-327/85015

The enclosed licensee event report provides details concerning the failure to comply with the one-hour fire watch requirement of Technical Specification 3.7.12. This event is reported in accordance with 10 CFR 50.73, paragraph a.2.i and special report requirements of Technical Specification 3.7.12.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


P. R. Wallace
Plant Manager

Enclosure
cc (Enclosure):

J. Nelson Grace, Regional Administrator
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30323

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, NUC PR, Sequoyah

1E22
11