



**CENTERIOR
ENERGY**

6200 Oak Tree Boulevard
Independence OH
216-447-3100

Mail Address
P.O. Box 94661
Cleveland, OH 44101-4661

Docket Number 50-346

License Number NPF-3

Serial Number 2399

August 22, 1996

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Inservice Inspection Summary Report of the Davis-Besse Refueling
Outage Activities
Davis-Besse Nuclear Power Station - Unit 1

Ladies and Gentlemen:

In accordance with the 1986 Edition of the American Society of
Mechanical Engineers (ASME) Boiler and Pressure Vessel Code Section
XI, IWA-6000, enclosed is the subject report covering inservice
inspection activities, and repairs and replacements completed through
the end of the Davis-Besse Nuclear Power Station, Unit 1 tenth
refueling outage.

Should you have any questions concerning this response, please
contact Mr. James L. Freels, Manager - Regulatory Affairs, at (419)
321-8466.

Very truly yours,

J. K. Wood
Vice President - Nuclear
Davis-Besse Nuclear Power Station

DLM/tam

Enclosure

9609040195 960822
PDR ADOCK 05000346
G PDR

cc: L. L. Gundrum, NRC Project Manager
A. B. Beach, Regional Administrator, NRC Region III
S. Stasek, DB-1 NRC Senior Resident Inspector
Factory Mutual Engineering Associates (2)
Ohio Department of Industrial Relations
Utility Radiological Safety Board

Operating Companies
Cleveland Electric Illuminating
Toledo Edison

A0471