

UNIT SHUTDOWNS AND POWER REDUCTIONS  
REPORT MONTH APRIL 1996

DOCKET NO. 50-440  
UNIT NAME Perry One  
DATE 6/14/96  
CONTACT G.M. Neuman  
TELEPHONE (216) 280-5815

NO.	DATE	TYPE 1	DURATION HOURS	REASON 2	METHOD 3	LER #	SYSTEM 4	COMP. 5	C. SE & CORRECTIVE ACTION TO PREVENT RECURRENCE
96-03	5/11/96	F	9.9	A	9	N/A			Turbine off line, EHC leak.
96-04	5/30/96	F	41.8	A	3	96-05	1R23		Aux. Transformer Fault.

SUMMARY: Perry Unit One was on-line for 692.3 hours during the month of May. The turbine was taken off-line on 5/11/96 to repair EHC leak. Back on-line the same day. The unit experienced an automatic scram due to an Auxiliary Transformer fault on 5/30. The unit remained shutdown through months end.

- |                                       |   |  |   |
|---------------------------------------|---|--|---|
| 1. TYPE:<br>F: Forced<br>S: Scheduled | 2. REASON:<br>A-Equipment Failure (explain)<br>B-Maintenance or Test<br>C-Refueling<br>D-Regulatory Restriction<br>E-Operator Training &<br>License Examination<br>F-Administrative<br>G-Operational Error (explain)<br>H-Other (explain) | 3. METHOD<br>1-Manual<br>2-Manual Scram<br>3-Automatic Scram<br>4-Continued<br>5-Reduced Load<br>9-Other | 4. EXHIBIT G- Instructions<br>for preparation of data<br>entry sheets for Licensee<br>Event Report (LER) file<br>(NUREG 1022)<br><br>5. EXHIBIT 1-Same Source |
|---------------------------------------|---|--|---|