

A-125
50-348/364-CIVP
5/20/92

APCO BX 125

0102443

DUCKETED
USNR

Wed Feedback 11/18/87 (23 people, 50 min)

'92 JUN -2 P12:10

Wilson: ASCO SOV - ~~small~~ small Q's re instal. data. Have ~~best~~ life - considering it.
PORV SOV?

DUCKETING & SERVICE
BRANCH

Accuracy - Methodology - don't have W methods or criteria - will get a WCAP #
understand what you have and are considering -
clearly problems in documenting qualif in this reg.

Raychem + Choco seal - Early in review - Q's out - need drawings + plant process
will be a 50.49 qualif problem

Hanek: EPA - GE + W TB types not verified

Levis: Limitorgues • Taroins - ^{113 cost + PMSVR} not yet established - package being revised - disagree - Td
• LS qual in ~~4~~ ^{adapters} with LS compartment down, thus not drainable

Fan motor - plastic shipping cap + possible used for breather drain valve

Jacobus: TBA - ^{states} 1/8" NPT test used top + side conduit, but no IR or leakage current w/out
Connection TB test by Conax - multiple side, no top, different block
10⁷ ohms generic can't sold readily
GE blocks = ? don't know what pkg tries to qualif
Foxboro blocks = ?

Cable - nothing major open now

Walker: Foxboro TB Q's out

Harsh environment definition (response not yet reviewed)

RTD vs T/C similarity

Paul

Smith: ASCO - several open items - cold S/D? - unit 2 qual life problem - maintenance

also for other
components

Procurement: 240,000 ft Okonite cable purchased to non-APCO-approved spec - not resolved

Cable C LS+TS installed in Ltps