



Entergy Operations, Inc.
P.O. Box 9
Boston, MA 02006
Tel: (617) 739-6774

R. F. Burski
(Director)
Head of Safety
Washington, D.C.

W3F1-92-0406
A4.05
QA

September 22, 1992

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Subject: Waterford 3 SES
Docket No. 50-382
License No. NPF-38
NRC Inspection Report 92-01
Schedule Information

Gentlemen:

As reflected in NRC Inspection Report 92-16, Waterford 3 and NRC representatives agreed that additional corrective action was necessary to fully address violation 9201-01.

To that end, Waterford 3 will revise Administrative Procedure UNT-005-004, "Temporary Alteration Control," such that the procedure includes appropriate guidance with regard to the administrative aspects of temporary alteration control.

The revision to UNT-005-004 will be complete by October 28, 1992.

Should you require any additional information or assistance, please contact T.W. Gates at (504) 739-6697.

Very truly yours,

RFB/TWG/ssf

cc: J.L. Milhoan, NRC Region IV
D.L. Wigginton, NRC-NRR
N.S. Reynolds
R.B. McGehee
NRC Resident Inspectors Office

9209240316 920922
PDR ADOCK 05000382
Q PDR

TEO 1/0