



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

DEC 3 1992

License No. SMB-911  
Docket No. 40-7580

Fansteel, Inc.  
ATTN: John J. Hunter  
Corporate Manager of Process  
Engineering and Facilities  
Construction  
Number Ten Tantalum Place  
Muskogee, Oklahoma 74401

Gentlemen:


SUBJECT: RESPONSE TO NRC INSPECTION REPORT NO. 40-7580/91-01  
(NOTICE OF VIOLATION)

This refers to your letter dated February 7, 1992, regarding NRC Inspection Report 40-7580/91-01 dated December 23, 1991. Given the low level of work activities at the site and the fact that operations have ceased, we accept your reply. However, once decommissioning and remediating activities commence in accordance with an approved plan, we expect you to review your activities to ensure compliance with your license and decommissioning plan.

No further response to this matter is required.

If you have any questions we will be pleased to discuss them with you.

Sincerely,

  
L. J. Callan, Director  
Division of Radiation Safety  
and Safeguards

cc:  
Oklahoma Radiation Control Program Director

9212090046 921203  
PDR ADOCK 04007580  
C PDR

IE07  
111

Fansteel, Inc.

-2-

bcc w/copy of licensee letter:

DMB - original (IE-07)

JLMilhoan

LJCallan

JPJaudon

Rodriguez, OC/LFDCB (4503)

WLFisher

CLCain

GMVasquez

NMLS

MIS System

RIV Files (2)

REHall, URFO

RIV NMIS	C:NMLS	D:DRSS		
GMVasquez <i>W</i>	WLFisher <i>W</i>	LJCallan		
12/1/92	12/1/92	12/2/92		

Fansteel, Inc.

-2-

bcc w/copy of licensee letter:

DMB - Original (IE-07)

JLMilhoan

LJCallan

JPJaudon

MRodriguez, OC/LFDCB (4503)

WLFisher

CLCain

GMVasquez

NMLS

MIS System

RIV Files (2)

REHall, URFO

RIV:NMIS	C:NMLS	D:DRSS		
GMVasquez <i>hw</i>	WLFisher <i>hw</i>	LJCallan		
12/1/92	12/1/92	12/2/92		

080019