



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

NOV 27 1992

License: 42-1649-01  
Docket: 030-06432

Associated Wireline Services, Inc.  
ATTN: Robert Johnston  
Radiation Safety Officer  
P.O. Box 187  
Wichita Falls, Texas 76307

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 030-06432/92-01

Thank you for your letter of November 16, 1992, in response to our letter and Notice of Violation dated October 22, 1992. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,

Charles L. Cain, Chief  
Nuclear Materials Inspection Section

cc:  
Oklahoma Radiation Control Program Director

9212090049 921127  
PDR ADOCK 03006432  
C PDR

107  
11

Associated Wireline  
Services, Inc.

-2-

bcc:  
DMB - Original (IE-07)  
JLMilhoan  
LJCallan  
JPJaudon  
MRodriguez, OC/LFDCB (4503)  
WLFisher  
CLCain  
RALeonardi, NMIS  
NMIS  
MiS System  
RIV Files (2)  
REHall, URFO

RIV:NMIS <i>RA</i>	C:NMIS\inc	<del>B:DRSS</del>		
RALeonardi:nh	CLCain	LJCallan		
11 A-3/92	11 127/92	1 / 92		

Associated Wireline  
Services, Inc.

-2-

bcc:

DMB - Original (IE-07)

JLMilhoan

LJCallan

JPJaudon

MRodriguez, OC/LFDCB (4503)

WLFisher

CLCain

RALeonardi, NMIS

NMIS

MIS System

RIV Files (2)

REHall, URFO

RIV:NMIS <i>RR</i>	C:NMIS\mc	<del>B:DRSS</del>		
RALeonardi:nh	CLCain	LJCallan		
11 A5/92	11 127/92	1 / 92		

# ASSOCIATED WIRE LINE SERVICES, INC.


P. O. BOX 1187

PHONE 817 723-5052

WICHITA FALLS, TEXAS 76301

November 16, 1992

Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 400  
Arlington, Texas 76011-8064



Gentlemen:

SUBJECT: REPLY TO NOTICE OF VIOLATIONS:  
DOCKET NO. 030-06432  
LICENSE NO. 42-11649-01

VIOLATION A. On the job inspections for logging supervisors were conducted on November 2, 1992 and November 5, 1992, covering jobs done by different logging supervisors. Results were recorded and placed in a permanent file for review. Steps have been taken to prevent the recurrence of this violation by placing notices of annual inspections in various prominent places as reminders. We came in full compliance with this violation on November 5, 1992. NO future violations of this nature should occur.

VIOLATION B. Vehicle surveys are now being recorded to include the positions occupied by each individual in the vehicle as well as the exterior of each vehicle used to transport the licensed material. We came in full compliance with this violation November 2, 1992. Corrective steps have been taken by supplying additional forms for recording the above information and placing forms and notices in each vehicle. The above corrective steps should prevent further violations of this nature. All recorded surveys are being placed in a permanent file for inspection.

Should you desire additional information concerning this matter, please contact us.

ASSOCIATED WIRE LINE SERVICES, INC.

By: Robert Johnston  
R.S.O.

CC: U.S. NUCLEAR REGULATORY COMMISSION  
Attention: Document Control Desk

9211250046

45-6321