

UNION ELECTRIC COMPANY
1901 GRATIOT STREET
ST. LOUIS, MISSOURI

August 10, 1979

JOHN K. BRYAN
VICE PRESIDENT

MAILING ADDRESS:
P. O. BOX 148
ST. LOUIS, MISSOURI 63166

Mr. James G. Keppler
Region III
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

ULNRC-322

Dear Mr. Keppler:

FINAL REPORT
DEFECTIVE SB12 AUXILIARY SWITCHES
CALLAWAY PLANT UNIT 1

In accordance with requirements of 10 CFR 50.55 (e),
we herewith submit our final report on the subject deficiency.

Preliminary notification of this deficiency was verbally
given to Mr. H. Westcott on July 13, 1979.

The attached report provides a description of the
defective material, the investigation at the Callaway jobsite,
and the corrective action to resolve the deficiency.

Very truly yours,

John K. Bryan
John K. Bryan

MHH/blm

cc: H. Westcott, Region III w/a
B. H. Grier, Region I w/a
Director, Office of I&E w/a
K. V. Seyfrit, Region IV w/a
W. A. Hansen, Region III w/a

3019
S
111

7908200 292