



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

DEC 1 1992

License: 35-15794-01  
Docket: 030-09794

State of Oklahoma  
Department of Transportation  
ATTN: Vance L. Poteet, Safety Manager  
200 N.E. 21st Street  
Oklahoma City, Oklahoma 73105-3204

Gentlemen:

SUBJECT: RESPONSE TO NRC INSPECTION REPORT NO. 030-09794/92-01  
(NOTICE OF VIOLATION)

Thank you for your letter of November 13, 1992, in response to our letter and attached Notice of Violation both dated October 27, 1992. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine whether full compliance has been achieved and will be maintained.

Sincerely,

*Charles L. Cain*

Charles L. Cain, Chief  
Nuclear Materials Inspection Section

cc:  
Oklahoma Radiation Control Program Director

070124

9212090140 921201  
PDR ADOCK 03009794  
C FDR

*IEO 7*  
*11*

bcc w/copy of licensee's letter:

DMB - Original (IE-07)

JLMilhoan

LJCallan

JPJaudon

MRodriguez, OC/LFDCB (4503)

WLFisher

CLCain

LMcLean

NMIS

MIS System

RIV Files (2)

REHall, URFO

*RIV:NMIS	*C:NMIS		
MLMcLean:nh	CLCain		
/ /92	/ /92		

\*Previously concurred

bcc w/copy of licensee's letter:

DMB - Original (IE-07)

JLMilhoan

LJCallan

JPJaudon

MRodriguez, OC/LFDCB (4503)

WLFisher

CLCain

LMcLean

NMIS

MIS System

RIV Files (2)

REHall, URFO

*RIV:NMIS	*C:NMIS		
MLMcLean:nh	CLCain		
/ /92	/ /92		

\*Previously concurred

State of Oklahoma

-2-

bcc w/copy of licensee's letter:

DMB - Original (IE-07)

JLMilhoan

LJCallan

JPJaudon

MRodriguez, OC/LFDCB (4503)

WLFisher

CLCain

LMcLean

NHIS

MIS System

RIV Files (2)


REHall, URFO

RIV:NMIS	C:NMIS <i>one</i>		
LMcLean:nh <i>WJW</i>	CLCain		
11/30/92	11/30/92		

PREVIOUS CONCURRENCE PAGE



STATE OF OKLAHOMA  
DEPARTMENT OF  
**TRANSPORTATION**  
200 N. E. 21st Street  
Oklahoma City, OK 73105-3204



November 13, 1992

Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive  
Suite 400  
Arlington, TX 76011-8064

RE: Reply to a Notice of Violation

Item A. CfR 20.207(A)

1. Reason for Violation - A gauge operator failed to lock the storage cabinet. The area is a garage adjacent to the work stations.
2. Corrective Steps - Construction Engineer wrote a reminder to all Resident Engineers/Branch Managers to emphasize compliance with rules and regulations. I visited the Residency 11-12-92 and discussed the violations and reasons for adherence with Directives.
3. Steps to Avoid Further Violations The Safety Branch will do quarterly inspections of each Residency to verify conditions and compliance.
4. We have accomplished these changes and emphasis 11-13-92

9211240396 Spp

93-0318


Reply to a Notice of Violation  
November 13, 1992

ITEM B. 10 CFR 19.1(A)

1. Reason for violation - We thought we had posted everything necessary.
2. Corrective Steps - The Construction Engineer issued a set of all required posters with his letter 11-4-92.
3. Steps to Avoid Further Violations:  
The Safety Coordinator will check these requirements along with gauges etc. during his quarterly inspections.
4. Compliance with (B) accomplished 11-5-92.

We hope these are satisfactory solutions to the violations found and we will strive for continued compliance with our license requirements.

Sincerely,



Vance L. Poteet  
Safety Manager

VLP/djj

Attachments

1. Copies of letters from the Construction Engineer
2. Copy of our poster describing documents available at each location.

cc: US Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555