

APPENDIX A

NOTICE OF VIOLATION

Department of the Army
USA MRIID
Fort Detrick
Frederick, Maryland 21702-5011

Docket No. 030-32476
License No. 19-11831-01

As a result of the inspection conducted on November 9, 1992, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1992), the following violation was identified:

License Condition No. 15 of NRC License NO. 19-1183-01 requires that licensed materials be used in accordance with the statements, representations and procedures contained in a letter dated February 25, 1992.

Section 3.0 of the letter requires that radiation detection instruments be calibrated annually.

Contrary to the above, as of November 9, 1992 a Victoreen Model 808D Area Monitor (Serial No. 570) which was in use had not been calibrated since September 9, 1991, a time period greater than one year.

This is a Severity Level IV violation. (Supplement IV)

Pursuant to the provisions of 10 CFR 2.201, Department of the Army USA MRIID is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.